

FRED SHEARER & SONS, INC. ESTABLISHED 1916

Job Hazard Analysis			JHA # 5
Job/Task Title: Wallboard Installation			
Safe Job Procedure:			Revised 11/2024
	nd successful operation of inst iques, cut prevention, and usi		
WORKERS MUST	READ AND UNDERSTAND) JHA #0 BEFORE E	BEGINNING ANY TASK
	er Scaffolds, #23 Power Tools terial Handling, #30 Covering/		
Step #1 Drywall Installati	on		
Steps to Complete Job	Hazards	Preventive Measures	
Install drywall to walls	Worker has the potential	1) Additional PPE: Cut level 4 gloves. When	
and ceiling framing.	to be exposed to strains,	overhead work produces particles, gasketed	
	sprains, cuts, trips, flying	safety glasses or a clear face shield with safety	
	debris and falls.	glasses are to be worn.	
		2) Use proper lifting techniques. Lift with legs and square up with the work. Avoid twisting	
		while lifting.	
		3) Avoid overreaching while using screw gun or	
		router.	
		4) All benches MUST have leg locks installed. Benches will be inspected by the foreman before being allowed on the jobsite. Benches will then be inspected daily, prior to each use the bench top should be clear of debris, and the path leading to the bench and area around the bench must be clear of debris.	
	Worker has the potential	1) Hearing protection is strongly recommended.	
	to be exposed to electrical	Hearing protection is required when noise	
	hazards, loud noise.	exceeds of 85db.	
		2) Ensure the task area has proper ventilation. Use an N-95 dust mask as needed.	
		3) Inspect electrical tools and charger cords for defects or damage prior to use. Red tag and	
		replace as needed.	
		4) Sprinkler heads must be protected by others	
		before installing board around them.	
		5) When using a router overhead, position body	
	away from debris field to avoid getting dus		
		eyes.	
		6) When finished in an area broom sweep using	
	Kleene Sweep or N-95 dust mask.		