

## FRED SHEARER & SONS, INC. ESTABLISHED 1916

Job Hazard Analysis			JHA # 30
Job/Task Title: Cov	vering and Cleanup		
Safe Job Procedure:			Revised 11/2024
This JHA is for the safe an	d successful covering of existi	ng or new finishes ar	nd the cleanup of the jobsite.
Emphasis is placed on we	aring the proper PPE and dust	management.	
WORKERS MUST I	READ AND UNDERSTAND	JHA #0 BEFORE E	BEGINNING ANY TASK
	Review JHA: #26 Ma	aterial Handling	
Step #1 General Jobsite C	overing		
Steps to Complete Job	Hazards		entive Measures
Covering and protecting	Worker has the potential	1) Stretch and flex before beginning of shift	
both new and existing finishes.	to be exposed to strains	after lunch. Stretch throughout the shift when	
	and sprains.	needed to reduce or eliminate muscle strains.  2) Use proper lifting techniques and get help with	
	2) Use proper lifting technique heavy awkward loads.		
		3) Avoid twisting while lifting.	
	Worker has the potential	1) Secure all covering materials so they do not create a trip hazard or nuisance hazard.	
	to be exposed to trips, falls	Create a trip flazard of flusarice flazard.     Create appropriate access and egress points	
	and being struck-by.	that will accommodate workers and the work being performed.	
		3) Eliminate any hazard or potential for hazard	
		before covering it.	
		4) Covered material must be secured against any	
		inclement weather or possible trade damages.	
		5) Follow proper knife safety when cutting paper	
		or plastic. Use of a retractable blade is	
		recommended.	
Step #2 General Jobsite C	leanup		
Steps to Complete Job	Hazards	Preventive Measur	es
Cleaning up the jobsite.	Worker has the potential		ciency, Plan the clean up so
	to be exposed to slips,	cleaning does not have to be repeated.  2) Fold covering material into itself, so loose	
	trips, falls, struck-by, and		
	cut hazards.	material does not fall onto floor and dust is	
		contained.	
		3) Place covering material and debris	
		immediately into dump buggies.  4) Use "Kleene Sweep" or similar additive when	
		sweeping to minim	
		5) Use floor scrapers for material that has	
		adhered to the floo	
			••